## **PATENT**

## IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

Patent No.: 7,262,947

Issued: August 28, 2007

Name of Patentee: Oliver Heravi; Mitchell R. Lawson

Title of Invention: LOW VOLTAGE INTERRUPTER FOR ELECTRIC WINCH

Confirmation No.: 7916

Attorney Docket: 7382-000051

Attn: Decision and Certificate of Correction

and insert -- has -- therefor.

Branch of the Patent Issue Division

Director of the USPTO

P.O. Box 1450

Alexandria, VA 22313-1450

	REQUEST FOR CERTIFICATE OF CORRECTION OF PATENT FOR APPLICANT'S MISTAKE (37 C.F.R. § 1.323)
1.	It is noted that errors appear in this patent of a clerical typographical minor
	nature or character, as more fully described below. It occurred in good faith Correction thereof does not involve such changes in the patent as would constitute new matter or would require re-examination. A certificate of correction is requested.
2.	Attached hereto, in duplicate, is Form PTO-1050, with at least one copy being suitable for printing.
3.	The exact page and line number where the errors occur in the application file are:

Page 8, line 2 of the application (col. 4, line 21 of the patent), please delete "bas"

4. Please send the Certificate to: Ryan W. Massey, Esq. Harness, Dickey & Pierce, P.L.C. P.O. Box 828 Bloomfield Hills, MI 48303 5. Please pay the fee required by 37 C.F.R. § 1.20(a)-\$100.00, as follows: Attached is a check money order in the amount of \$ 冈 Authorization is hereby made to charge the amount of \$100.00 to Deposit Account No. 08-0750 to Credit card as shown on the attached credit card information authorization form PTO-2038 Charge any additional fees required by this paper or credit any overpayment to Deposit Account No. 08-0750. Respectfully submitted, Dated: November 29, 2007 Electronic Signature: /Ryan W. Massey/ Ryan W. Massey, Reg. No. 38,543

HARNESS, DICKEY & PIERCE, P.L.C. P.O. Box 828 Bloomfield Hills, Michigan 48303 (248) 641-1600 Under the Paperwork Reduction Act of 1995, no persons are required to respond to a collection of information unless it displays a valid OMB control number. (Also Form PTO-1050)

## UNITED STATES PATENT AND TRADEMARK OFFICE

CERTIFICATE OF CORRECTION PATENT NO: 7,262,947 **APPLICATION NO: 10/799,141** DATED: March 12, 2004 (Issued August 28, 2007) INVENTOR(S): Heravi et al It is certified that error appears in the above-identified patent and that said Letters Patent are hereby corrected as shown below: Col. 4, line 21, please delete "bas" and insert --has-- therefor.

MAILING ADDRESS OF SENDER:

Ryan W. Massey Harness, Dickey & Pierce, P.L.C. P.O. Box 828 Bloomfield Hills, MI 48303

PATENT NO. 7,262,947

No. of additional copies



This collection of information is required by 37 CFR 1.322, 1.323, and 1.324. The information is required to obtain or retain a benefit by the public which is to file (and by the USPTO to process) an application. Confidentiality is governed by 35 U.S.C. 122 and 37 CFR 1.14. This collection is estimated to take 1.0 hour to complete, including gathering, preparing, and submitting the completed application form to the USPTO. Time will vary depending upon the individual case. Any comments on the amount of time you require to complete this form and/or suggestions for reducing this burden, should be sent to the Chief Information Officer, U.S. Patent and Trademark Office, U.S. Department of Commerce, P.O. Box 1450, Alexandria, VA 22313-1450. DO NOT SEND FEES OR COMPLETED FORMS TO THIS ADDRESS. SEND TO: Attention Certificate of Corrections Branch, Commissioner for Patents, P.O. Box 1450, Alexandria, VA 22313-1450.